

meeting a held under the chairmanship of
Smt. Rukmesh Kumar Sarpanch for half an
upper margin to discuss the status of project
and the progress for the year 2023-24.
All the parties including general public attended
the meeting. In the meeting village sanitation
plan is also discussed. Sanitation committee
is also formulated in the gram
sanita as decided by the higher authorities.
The gram sanita proposed the following works
to be included in the sheet of project
of MGNREGS for the year 2023-24.

- (1) Const. of B/Path at Rambrishon Moh. w-No-1 1.00
- (2) Const. of T/Road from M/Road Narot kur Moh to 1.50 km
Tidale Raj Moh w-No-1
- (3) Const. of well at w-No-01 2.00
- (4) Const. of F/Path at Dav Sthan w-No-01 1.50
- (5) Const. of D/Channel at Ghat. Ashok kur Moh w-No-1 1.50
- (6) Land levelling & Allied Allied works at Rajist
Kumar Moh. w-No-1. 1.00
- (7) Imp of T/Road with Allied works from M/Road to 1.50
Baba Nar Singh Pt. Jagdish kur Moh.
- (8) Const. of F/Path at Tara Chand Moh. Kur Moh 1.50
- (9) Const. of T/Road M/Road to Mohaigan Moh 1.50
- (10) Const. of D/Channel at Ashok kur Moh w-No-1 1.50
- (11) Const. of Cattle shed at ~~Dehat~~ Moh. w-No-1 0.50
- (12) Const. of Cattle shed at w-No-01. Narot kur 0.50

- (13) Const. of T/Road M/Road to Moh. Shom Lal w-No-2 1.00
- (14) Const. of Pond at ~~Moh~~ Shom Lal Moh 2.00
- (15) Const. of Pond at Pindam Chand Moh 2.00
- (16) Const. of well N/ Pindam Chand Moh 2.00
- (17) Repair of well N/ Radhey Shom Moh 2.00
- (18) Const. of well N/ Suraj Kumar of Pindam Moh 2.00
- (19) Const. of Platform of well at Moh Shom Lal 1.00
- (20) Const. of well N/ Suraj of Pindam Moh 2.00
- (21) Const. of Cattle Shed Moh Khandesh Kur Moh 0.50
- (22) Const. of well at Ghat Moh 2.00
- (23) Repair/ Maintenance of Pindam N/ Pindam kur Moh 0.50
- (24) Const. of well N/ Sot Pond Moh. 2.00
- (25) Const. Repair of Road from Moh ~~Khandesh~~ Kur Moh to
Darn to Shom, harghet. 1.00
- (26) Const. of well N/ Ram Shom Moh. 2.00
- (27) Const. of Cattle Shed at Toshi Davi Moh. 0.50

w-No-03

(17) Const. of B/Rth khaizer to Taradiga. 1.50

(W. No-07)

- (1) Const. of well N/ Suresh Moh. 2.00
- (2) Imp. of Road from Thanger to Shomshengad 1.00
- (3) Const. of T/Road Tadoni to Shomshengad Moh. 1.00
- (4) Extension/Imp. of T/Road ~~to~~ Kestui Moh. 1.00 to Giam Chand Moh.
- (5) Bul. work of T/Road ~~to~~ Moh. Kewal Krishan Moh. to Mahesh Moh. 1.00
- (6) Const. of T/Road Sardona to Tadoni. 1.00

The following Panches and Prominent Persons were present in the meeting :-

- | | | |
|---|---|--------------------|
| (1) Sh. Ram Parkash (Panch w. No-1) | - | Sh. Ram Parkash |
| (2) Sh. Subash Chander (Panch w. No-07) | - | Sh. Subash Chander |
| (3) Shom Lal | - | Shom Lal |
| (4) Sh. Ramesh Chander (Panch w. No-08) | - | Ramesh Chander |
| (5) Neema Devi (Panch w. No-08) | - | NEEMA DEVI |
| (6) Jee Singh | - | Jee Singh |
| (7) Ram Lal (Panch w. No-07) | - | Ram Lal |
| (8) Renu Bala (Panch w. No-05) | - | Renu Bala |
| (9) Raj Lal (ex Sarpanch) | - | Raj Lal |
| (10) Kamlesh Kumar | - | Kamlesh Kumar |
| (11) Lala Devi (Panch w. No-2) | - | Lala Devi |
| (12) Bhole Singh | - | Bhole Singh |

- (2) Const. of T/Read Stem (at Moh. to Pasli Gali) 1.50
 (3) Const. of well N/ Parsharam Singh Moh. 1.00
 (4) Imp. Const. of T/Read Raj kr. Moh. to Sharnahangal 2.00
 (5) Imp. of well N/ Pritham Singh Moh. W-No-04 1.50
 (6) Const. of well at W-No-04 2.00
 (7) Const. of Chai at N/ Charnall Singh Moh. 2.00
 (8) Const. of well N/ Sham Lal Moh. 1.00
 (9) Const. of well N/ Kumbhar Singh Moh. 2.00
 (10) Const. of B/Path Gurnail Singh Moh. to Lakshmi Lal Moh. 2.00
 (11) 1.50 ias

W-No-07

- (1) Const. of B/Path from Malwa to Bung. 1.00
 (2) Repair of T/Read from Pawal School to Ambikhar via Raja Mandlik Mahom. 1.00
 (3) Const. of T/Read from Ambikhar to Sharnahangal 1.00
 (4) Land levelling at Karmesh Kumar Moh. 1.00
 (5) Land levelling at Ambikhar Moh. 1.00
 (6) Land levelling at Karmala & Malward Moh. 1.00
 (7) Bat. work of well at Kanka Thull. 1.00
 (8) Const. of Pond at Karmala. 1.50

(W-No-05)

- (1) Imp. Repair of Baul at W-No-05 0.50
 (2) Imp. Extension of T/Read from S. Moh. to Chhapan 1.00
 (3) Const. of well at Ram Puri Moh. 2.00
 (4) Const. of well N/ Sam Raj Moh. (W-No-05) 2.00 ias
 (5) Const. Extension of T/Read from M/Read to Turo Mandir (W-No-05)
 (6) Const. of T/Read from Sardona to Badli Lal Moh. 1.00
 (7) Const. of Gille. Stud at Gulshan Kumar 0.35

(W-No-06)

- (1) Const. of well at Pritham Singh Moh. (W-No-06) 2.00
 (2) Const. of B/Path M/Read to Village Lal Moh. 1.50 ias
 (3) Const. of T/R M/R to Nirmala Devi Moh. Trambli 1.00
 (4) Imp. of Road from M/R to Raja Mandlik 1.00
 (5) Const. of T/Read M/R to Rangil Singh Moh. 1.50
 (6) Const. of T/Read M/R to Rakhon Lal Moh. 1.50
 (7) Const. of D/Channel M/R to Dew Raj Moh. 1.50
 (8) Const. of Baul N/ Ram Lal Moh. 0.50
 (9)

(W-No-08)

- (1) Const. of T/Read from Deigan Tibbi to Khajari Moh. 1.00
 (2) Land levelling / filled works at in the I/c Raj Kumar Moh. 1.00
 (3) Imp. of Pond at N/ Ration Lal Moh. 1.00
 (4) Const. of B/Path from Rendi to Ram Nar Singh 1.00
 (5) Const. of P/work at W-No-08. 1.50
 (6) Const. of P/work at Yand Moh. 1.50
 (7) Imp. of well at Ghajra 1.00
 (8) Land levelling at Turo Mandir, Badli Kumar 1.00