

Back to the Village Report

(Format to be filled up by the Reporting Officer during
his/her two day visit to the Gram Panchayat)

A) DETAILS OF REPORTING OFFICER:

- i. Name: SHAMUS U DIN PIR.
- ii. Designation: Headmaster.
- iii. Department/ place of posting: Education. EHS/Kradpora.
- iv. Mobile No: 9697009072.
- v. Email id: —
- vi. Home District: Kupwara.
- vii. Dates of visit: 20/21/22/23/24/25/26/27, June 2019

B) LOCATIONAL DETAILS OF GRAM PANCHAYAT:

- i. Name of the Gram Panchayat (GP): Trehgam 'E'
- ii. Local Government Directory (LGD) code of the GP: 239338.

(To be sourced from Rural Development Department/ by DC)

- iii. Name of CD Block: Trehgam.
- iv. Name of Tehsil: — Threhgam.
- v. Name of District: Kupwara.

C) PANCHAYAT PROFILE:

- i. Name(s) of revenue villages in the Gram Panchayat:
 1. Trehgam.
 2. —
 3. —
 4. —
 5. —
- ii. No. of hamlets in the GP: — 07.
- iii. No. of households in the GP: — 234.
- iv. Population (approx) of the GP: — 2264.
- v. Significant geographical feature of the GP (hilly/ kandi/ plain): ✓
- vi. Key natural resources of the GP (forest/ water bodies/ minerals/ others/ None): ✓

D) KEY AMENITIES IN THE GRAM PANCHAYAT:

1. STATUS OF ROADS:

- i. Whether Gram Panchayat is connected with road (Yes/No): ☒ Yes
- ii. If yes, type of existing road connecting to GP (Tick one):
 - a) ☒ Black topped/ ☐ Metalled/ ☐ Shingled/ ☐ Fair-weather,
 - b) Remarks: one road of mukdam Mohalla damaged.
- iii. Condition of existing road connecting to GP (Tick one):
 - a) ☒ Good/ ☐ Average/ ☐ Dilapidated
 - b) Remarks: _____
- iv. General condition of internal roads/ link roads inside the GP (Tick one):
 - a) ☐ Good/ ☐ Average/ ☐ Dilapidated/ ☐ No internal roads as the area is hilly.
 - b) Remarks: Road of mukdam Mohalla needs reconstruction.
- v. Unconnected habitations having population of 250 or more souls (with name):
 - a) Number: _____
 - b) Names- (i) New Colony (Malik Mohalla)
(iii) X (iv) X (v) X
- vi. Requirement of/ need for construction/ up-gradation of roads/ bridges/ culverts [with name/ length (Max. 03 works)]:

Name of the road/ bridge/ culvert	Approx. Length in Kms/ Mtrs
1. Bridge (mukdam Mohallah ON Nalla. Mool. Kul.	
2. Road connectivity from Trehgam To Baba gund.	
3. Construction of damaged road mukdam. Mohalla.	

2. DRINKING WATER/ WATER BODIES:

- i. Source of drinking water (Tick as many as needed):
 - a) ☒ Tapped Water/ ☐ Tube well/ ☐ Dug well / ☐ Natural Source (spring, nallah, bowli, river)/ ☐ Hand Pump Needs re-construction because of very old scheme overall damaged hence needs reconstruction.
 - b) Others (please specify): _____

E) GENERAL ASSESSMENT OF THE VISITING OFFICER:

I	Main economic activities/ source of livelihood in the GP (Max. 05):
1.	Farming.
2.	Labour.
3.	Business.
4.	Govt. employees.
5.	Carpentry/masonry.
II	Major potential areas which can be used to improve economic conditions in the GP (Max. 05):
1.	Hilly area available to be leveled.
2.	Damage Agriculture land by floods.
3.	Road connectivity to hilly land.
4.	Nalla Rahmud box both sides strongly bunded.
5.	Fish ponds.
III	Major problems confronting the people in the GP (Max. 05):
1.	Not any Govt. institution in E.P.
2.	Panchayat Building be constructed.
3.	Community hall be constructed.
4.	Food store be established.
5.	Four ACD (centres be allotted)

IV	Urgent public requirements in order of priority (Max. 07):
	Babajum 1. Road connectivity from Trehgam to 2. Link road to Mounchkhoul to Lone mshalla 3. Link road from Nivampora to Alpuzi (Baba gund) 4. Link road from stadium to BSF Fixing Batha. 5. Mukdam mshalla Bridge on Nala maul Kul. 6. Womens College Trehgam (land available) 7. Electric Transformers with 50 poles (AFV)
V	Any major complaint brought to notice: other material, (New colony)
	Irrigation dept. regarding negligence of new duty Agriculture/Horticulture/Animal/sheep husbandry. R & B dept.
VI	Overall assessment of visit (Public Services): Please mention best practices, if any, observed
	All the employees participated & co-operated fully in all respects. people participated in gram sabah with great & wide interaction & discussions. people co-operated fully and gram sabah was conducted smoothly & colony programme was very appreciated & welcomed. people hope for practical implementation.
VII	Overall assessment of visit (Panchayat functioning)
	Pachayat Ghar not available. meetings are conducted either in private buildings or in open areas. Non availability of pachayat ghar causes hindrance in panchayat functioning.

Signature of the visiting officer

Name Shamir uddin

Prv.