





# Back to Village 2

B2V2

**Governance at the Doorstep**

November 25-30, 2019



**Government of Jammu & Kashmir**

*Mohalla through M. Sedy Lone.*

## Back to the Village Report

(Format to be filled up by the Reporting Officer during  
his/her two day visit to the Gram Panchayat)

### A) DETAILS OF REPORTING OFFICER:

- i. Name: Mr. Raja Waseem Mohd. Makroo
- ii. Designation: Assistant Executive Engineer
- iii. Department/ place of posting: MID, Hajin Sub-Division
- iv. Mobile No: 9797249703
- v. Email id: aee.midsdhajin@gmail.com
- vi. Home District: Pulwama
- vii. Dates of visit: 20/21/22/23/24/25/26/27. June 2019

### B) LOCATIONAL DETAILS OF GRAM PANCHAYAT:

- i. Name of the Gram Panchayat (GP): Guzarbal
- ii. Local Government Directory (LGD) code of the GP: 242181

(To be sourced from Rural Development Department/ by DC)

- iii. Name of CD Block: Bonakoot
- iv. Name of Tehsil: Bandipora
- v. Name of District: Bandipora

### C) PANCHAYAT PROFILE:

- i. Name(s) of revenue villages in the Gram Panchayat:

1. Guzarbal 2. Parra-Mohalla 3. Beigh - Mohalla  
4. Lower Kunusa 5. Upper Kunusa 6. Bilal Colony 7. Kothari Mohalla

- ii. No. of hamlets in the GP: 03

- iii. No. of households in the GP: 343

- iv. Population (approx) of the GP: 1825

- v. Significant geographical feature of the GP (hilly/ kandi/ plain):

- vi. Key natural resources of the GP (forest/ water bodies/ minerals/ others/ None):

D) KEY AMENITIES IN THE GRAM PANCHAYAT:

1. STATUS OF ROADS:

i. Whether Gram Panchayat is connected with road (Yes/No) ✓

ii. If yes, type of existing road connecting to GP (Tick one):

a) Black topped/ Metalled/ Shingled/ Fair-weather

b) Remarks: The roads are not available and there is a high demand for same by locals.

iii. Condition of existing road connecting to GP (Tick one):

a) Good/ Average/ Dilapidated ✓

b) Remarks: Not existing, only pieces of road available and mostly foot paths with stone paving exist in GP.

iv. General condition of internal roads/ link roads inside the GP (Tick one):

a) Good/ Average/ Dilapidated/ No internal roads as the area is hilly. ✓

b) Remarks: The area is hilly and internal roads are not available and only footpaths exist.

v. Unconnected habitations having population of 250 or more souls (with name):

a) Number: 04

b) Names- (i) Bilal Colony (ii) Kunusa

(iii) Guzarbal (iv) Chan-Mohalla (v) \_\_\_\_\_

vi. Requirement of/ need for construction/ up-gradation of roads/ bridges/ culverts

(with name/ length (Max. 03 works)):

Name of the road/ bridge/ culvert Approx. Length in Kms/ Mtrs

1. Aham Sharief to Guzarbal via Kunusa through bridge

2. Chan-Mohalla to Guzarbal

3. Approx. 15 Culverts needed to be built at different locations in GP.

2. DRINKING WATER/ WATER BODIES:

i. Source of drinking water (Tick as many as needed):

a) Tapped Water/ Tube well/ Dug well/ Natural Source (spring, nallah, bowl, river)/ Hand Pump ✓

b) Others (please specify): The water available is not fit for drinking and no filtration plant/scheme is operational in GP.

## ASSESSMENT OF THE VISITING OFFICER:

Economic activities/ source of livelihood in the GP (Max. 05):

Agriculture based Activities

Kangri & Basket making using locally available material

Sheep & cattle rearing for milk and meat products.

Horticulture Activities include Apple Orchards

Silk farming / Cocoon farming.

potential areas which can be used to improve economic conditions in the GP (Max. 05):

Tourism sector can be tapped as this area has beautiful landscapes & scenery.

Sheep and cattle rearing can be encouraged to maximise the earnings of common people in order to raise their standard of living.

Fish farming & Duck farming can be encouraged as lot of water bodies such as fresh water tanks are present/available in GP.

Agriculture produce/yield can be maximised by implementing new scientific methods & modern technology

Poultry farming can be encouraged to improve economic conditions in the GP.

Major problems confronting the people in the GP (Max. 05):

The most critical problem in area is the non-availability of roads and GP is badly hit because of very poor road infrastructure

1. In case of fire, even fire brigades cannot reach the spot.

The soil erosion problem is faced by locals as the run away water from hilly areas has caused havoc and destruction in residential houses.

2. Unavailability of Health, ICDS, Animal/Sheep Husbandry centre.

3. Unavailability of proper and adequate school building

4. & food grains/cereals to be made available to MDM Centres

Non functional water filtration schemes has forced the people to consume dirty water leading to frequent

5. outbreak of diseases.

III Overall perception of functioning of the government:

Proper attention of Govt towards basic needs of Public and full support of related system. i.e. education, drinking water, health related facility, proper electricity and better communication.

IV Overall assessment of visit and suggestions:

(the visiting officer to ensure that the overall assessment is recorded in detail along with concrete suggestions.)

Rural area is based more on BPL families so needs subsidised schemes in large to eradicate poverty from rural areas and provision of education facilities on scientifically and to introduce technical schemes for rural unemployed youth with a good margin of subsidy and very low interest rates.

Signature of the visiting officer

Name Ab. Karim Shah

