

Back to the Village Report

(Format to be filled up by the Reporting Officer during his/her two day visit to the Gram Panchayat)

A) DETAILS OF REPORTING OFFICER:

- i. Name: SYED YOUNS Saleem
- ii. Designation: Assistant Engineer REW Tangmarg
- iii. Department/ place of posting: REW Tangmarg
- iv. Mobile No: 7086291013 / 9419075188
- v. Email id: Syed.youns.Bukhari@g-mail.com
- vi. Home District: Budgam
- vii. Dates of visit: 20/21/22/23/24/25/26/27. June 2019

B) LOCATIONAL DETAILS OF GRAM PANCHAYAT:

- i. Name of the Gram Panchayat (GP): Harduaboora A
 - ii. Local Government Directory (LGD) code of the GP: 241823
- To be sourced from Rural Development Department/ by DCI
- Name of CD Block: Harduaboora A
 - iii. Name of Tehsil: Karhama
 - v. Name of District: Baramulla

C) PANCHAYAT PROFILE:

- i. Name(s) of revenue villages in the Gram Panchayat:
1 Harduaboora 2 Kharpora 3 Hasipora
4 5
- ii. No. of hamlets in the GP: Gulasdaji (01)
- iii. No. of households in the GP: 654
- iv. Population (approx) of the GP: 3276
- v. Significant geographical feature of the GP (hilly/ kandi/ plain):
- vi. Key natural resources of the GP (forest/ water bodies/ minerals/ others/ None):

D) KEY AMENITIES IN THE GRAM PANCHAYAT:

1. STATUS OF ROADS:

- i. Whether Gram Panchayat is connected with road (Yes/No) ☒
- ii. If yes, type of existing road connecting to GP (Tick one)
 - a) Black topped/ Metalled/ Shingled/ Fair-weather ☒
 - b) Remarks: Needs upgradation from Hariduboor to other Revnew villages
- iii. Condition of existing road connecting to GP (Tick one)
 - a) Good/ Average/ Dilapidated ☒
 - b) Remarks: Needs upgradation
- iv. General condition of internal roads/ link roads inside the GP (Tick one):
 - a) Good/ Average/ Dilapidated/ No internal roads as the area is hilly. ☒
 - b) Remarks: Roads are in a deteriorated condition needs upgradation
- v. Unconnected habitations having population of 250 or more souls (with name):
 - a) Number: None / Nil
 - b) Names- (i) _____ (ii) _____
(iii) _____ (iv) _____ (v) _____
- vi. Requirement of/ need for construction/ up-gradation of roads/ bridges/ culverts [with name/ length (Max. 03 works)]:

Name of the road/ bridge/ culvert	Approx. Length in Kms/ Mtrs
1. Construction of Road from Haripora to wanigam via chede	= 5 km (all)
2. Construction of Road from H. aboor to Haripora via kharpora	= 8 kms
3. Inner links of village Hariduboor to Heeng	= 3 kms

2. DRINKING WATER/ WATER BODIES:

- i. Source of drinking water (Tick as many as needed):
 - a) Tapped Water/ Tube well/ Dug well / Natural Source (spring, nallah, bowli, river)/ Hand Pump ☒
 - b) Others (please specify): Improvement of springs

ii. Is the availability of drinking water sufficient? Yes/ No
No

iii. Quality of drinking water in the Gram Panchayat (Tick one)

a) Very Good/ Average / Not fit for consumption.

b) Remarks needs upgradation of filtration plant constructed in 1972

iv. Hamlets without tapped water supply (with name):

a) Number No

b) Names- (i) _____ (ii) _____

(iii) _____ (iv) _____ (v) _____

v. Coverage of households through tapped water:

a) Fully covered/ Substantially covered/ Partially covered/ Not covered

b) Remarks: Needs replacement of all old pipes.

vi. Frequency of water supply (for connected habitations) (fill one):

a) Daily (12 hrs/day)

b) Thrice a week (____ hrs/day)

c) Twice a week (____ hrs/day)

d) Weekly (____ hrs/day)

e) Remarks: needs improvement

vii. Prevalence of diseases on account of unhygienic water supply (as reported) (tick one):

a) Frequently/ Sometimes / Never

viii. Untapped water sources, details if any: NO

(i) well (ii) well

(iii) well (iv) well

ix. Necessity and further need regarding drinking water supply:

a. Demand for pipes (length): _____ (Kms)

$$4'' = 1.5 \text{ kms}$$

$$1'' = 1 \text{ km}$$

$$3/4'' = 1 \text{ km}$$

$$1\frac{1}{2}'' = 0.5 \text{ kms}$$